

GOVERNMENT OF ANDHRA PRADESH  
ABSTRACT

General Administration Department – Secretariat Buildings – Repairs to Room Nos.707, 708, 7<sup>th</sup> Floor and for partition in Chief Secretary's Peshi, 7<sup>th</sup> Floor, L-Block in the premises of A.P. Secretariat – Submission of estimate – Administrative Sanction – Orders – Issued.

---

GENERAL ADMINISTRATION (SB) DEPARTMENT

G.O.RT.No. 612

Dated: 28.02.2015

Read:-

From the Executive Engineer (R&B) Buildings Division, Hyderabad.  
Lr.No.EE(R&B) /Bldgs Division / AP SEC/2014-15, Dated: 18.2.2015  
&&&

ORDER:

In the circumstances reported by the Executive Engineer (R&B) Buildings Division Hyderabad in the reference read above and after examination of the matter, Government hereby accord administrative sanction for an amount of Rs.3,70,000-00 (Rupees Three Lakhs Seventy Thousand only) towards Repairs to Room Nos.707, 708, 7<sup>th</sup> Floor and for partition in Chief Secretary's Peshi, 7<sup>th</sup> Floor, L-Block in the premises of A.P Secretariat, Hyderabad on the responsibility of Executive Engineer (R&B) Buildings, Hyderabad and also subject to production of the work done certificate at the time of issue of L.O.C.

2. The expenditure shall be debited to the head of account "2059 Public works – 01 Office buildings - MH 053 Maintenance and repairs – SH(10) Buildings of General Administration Department – 270 Minor works – 272 Maintenance"
3. This order does not require the concurrence of Finance Department in terms of Circular Memo.No.7088/049/A/BG/2000-1, dated 25.10.2002.

(BY ORDER AND IN THE NAME OF THE GOVERNOR OF ANDHRA PRADESH)

MUKESH KUMAR MEENA  
SECRETARY TO GOVERNMENT  
(POLL.)

To

The Executive Engineer (R&B) Buildings Division, Hyderabad.

Copy to:

The Dy.E.E.(R&B) Buidlings, Sectt. Sub-Division.

//Forwarded By Order//

SECTION OFFICER